



SOPLETE PHB/PMB 20/50

DESPIECE SOPLETE PHB/PMB 20/50



SOPLETE PHB/PMB 20/50



SOPLETE PHB/PMB 20/50

DENOMINACIÓN		CÓDIGO	OBSERVACIONES
SOPLETE PHB 20/50 3M	1	244351.2	
SOPLETE PMB 20/50 3M	1	244359.3	
CUERPO. SOPL.PHB 20/50	1	247075.3	
CUERPO. SOPL.PMB 20/50	1	247076.4	
MANGO PHB-20/50	15	247080.1	
RETEN PHB 20/50	6	247077.5	
TAPA PHB 20/50	9	247078.6	
MUELLE CENTRADOR PHB 20/50	4	247079.0	
PINZA 1,0 PHB 20/50	7	247012.3	
PINZA 1,5 PHB 20/50	7	247021.5	
BOQUILLA 0.6 PHB 20/50	3	247039.2	
BOQUILLA 0.8 PHB 20/50	3	247006.4	
BOQUILLA 1.0 PHB 20/50	3	247007.5	
BOQUILLA 1.2 PHB 20/50	3	247008.6	
BOQUILLA 1.4 PHB 20/50	3	247040.3	
BOQUILLA 1.6 PHB 20/50	3	247041.4	
BOQUILLA 1.8 PHB 20/50	3	247042.5	
TUBO CERAMICO 1.0 PHB 20/50	14	247073.1	
TUBO CERAMICO 1.5 PHB 20/50	14	247074.2	
ELECTRODO TUNGST. 2%To 1.0X62	10	247043.6	
ELECTRODO TUNGST. 2%To 1.5X62	10	247071.6	
BOQUILLA GAS PHB 20/50	2	247005.3	
JUNTA 5X1.5 PHB 20/50	5	247044.0	
JUNTA TAPA PHB 20/50	8	247013.4	
CENTRADOR ELECTR. 1MM PHB	13	247016.0	
CENTRADOR ELECTR. 1.5 MM PHB	13	247017.1	
CENTRADOR ELECTRODO PHB	16	247072.0	

DATOS DE CONTACTO

© Copyright 2016 Praxair Technology, Inc. Todos los derechos reservados. Rev. 03/2018



Web: Soldadura.Praxair.es



Email: backoffice_soldadura_es@praxair.com



Teléfono: +34 952 36 31 59

